



# CONSTRUCTION EQUIPMENT

534598 GEN ASPHALT VOLVO L90H 623733 - COOLANT



**Sample No:** VCP437297  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 534598 GEN ASPHALT



## SAMPLE INFORMATION

Sample Number	VCP437297	---	---	---
Sample Date	15 Apr 2024	---	---	---
Machine Hours	12275	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
8418 PALM RIVER ROAD  
TAMPA, FL  
US 33619  
Contact: KENNY HANEY  
khaney@flaglerce.com  
T: (813)630-0077  
F: (813)630-2233



## COOLANT CONDITION

pH	Scale 0-14	■ 7.72	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.6	---	---	---
Freezing Point	°C	■ -33	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO0093  
**Unique No:** 11037082  
**Signed:** Jonathan Hester  
**Report Date:** 24 May 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

