

CONSTRUCTION EQUIPMENT 716086 GERDAU VOLVO L350H 1220 - FRONT AXLE



Sample No: VCP453556

Oil Type: VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102

Job No: 716086 GERDAU

SAMPLE	E INFORMATIO	N		
Sample Number	-	VCP453556	VCP426818	
Sample Date		15 May 2024	03 May 2023	
Machine Hours		7316	2659	
Oil Hours		3000	2659	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
VOLVO	DITION			
OIL CON				
Visc @ 40°C	cSt	40.6	□ 52.3	
CONTAN	MINATION			
Water	%	NEG	NEG	
Silicon		mg	112	
Sodium	ppm	■ <1	1 0	
Potassium	ppm	1 0	1	
Potassium	ppm		I I	
VOLVO				
WEAR N	METALS			
Iron	ppm	■34	118	
Copper	ppm	■ 0	2	
Lead	ppm	0	- <1	
Tin	ppm	■ 0	- <1	
Aluminum	ppm	■<1	4	
Chromium	ppm	■ 0	1	
Molybdenum	ppm	-<1	2	
Nickel	ppm	■ 0	- <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm		3	
Vanadium	ppm	0	0	
ADDITIV	VEC			
_				
Calcium	ppm	■2757	■3598	
Magnesium	ppm	14	7	
Zinc	ppm	1261	1500	
Phosphorus	ppm	1186	1172	
Barium	ppm	■0	0	
Boron	ppm	2	108	



ALTA EQUIPMENT COMPANY - METRO WEST
56195 PONTIAC TRAIL
NEW HUDSON, MI
US 48165
Contact: PAUL CONZ
paul.conz@altg.com
T: (313)348-8861
F: (248)356-2029

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO2990

 Unique No:
 11043297

 Signed:
 Wes Davis

 Report Date:
 22 May 2024



CONSTRUCTION EQUIPMENT





