



CONSTRUCTION EQUIPMENT

X14147 VOLVO A25G 752640 - REAR AXLE



Sample No: VCP399196
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: X14147



SCOTT EQUIPMENT COMPANY LLC - Broussard
 100 IDA ROAD
 BROUSSARD, LA
 US 70518
 Contact: ALISON HARGRODER
 ahargroder@scottcompanies.com
 T: (337)837-2907
 F: (337)837-5116



SAMPLE INFORMATION

Sample Number	VCP399196	---	---	---
Sample Date	17 May 2024	---	---	---
Machine Hours	1400	---	---	---
Oil Hours	500	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 89.2	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 4	---	---	---



WEAR METALS

Iron	ppm	█ 621	---	---	---
Copper	ppm	█ 28	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 10	---	---	---
Molybdenum	ppm	█ 17	---	---	---
Nickel	ppm	█ 4	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 14	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 852	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 368	---	---	---
Phosphorus	ppm	█ 1349	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 266	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO6241
Unique No: 11044780
Signed: Sean Felton
Report Date: 24 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS

