



CONSTRUCTION EQUIPMENT

701295 PRIMORIS VOLVO A40G 352509 - COOLANT



Sample No: VCP449860
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 701295 PRIMORIS



SAMPLE INFORMATION

Sample Number	VCP449860	---	---	---
Sample Date	12 Apr 2024	---	---	---
Machine Hours	6123	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



COOLANT CONDITION

pH	Scale 0-14	■ 7.26	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 45.9	---	---	---
Freezing Point	°C	■ -24	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---

Depot: VOLVO0093
Unique No: 11047660
Signed: Jonathan Hester
Report Date: 29 May 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

