



# CONSTRUCTION EQUIPMENT

SWA548445-20 VOLVO L60H 2528 - REAR AXLE



**Sample No:** VCP430344  
**Oil Type:** VOLVO WET BRAKE TRANSAXLE OIL  
**Job No:** SWA548445-20



## SAMPLE INFORMATION

Sample Number	VCP430344	---	---	---
Sample Date	17 May 2024	---	---	---
Machine Hours	2053	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

## ALTA EQUIPMENT

5985 COURT STREET ROAD  
 SYRACUSE, NY  
 US 13206  
 Contact: JIM STRIGLE  
 JIM.STRIGLE@ALTG.COM  
 T: (315)437-2611  
 F: (315)434-9471



## OIL CONDITION

Visc @ 40°C	cSt	█ 40.5	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 15	---	---	---
Sodium	ppm	█ 8	---	---	---
Potassium	ppm	█ 4	---	---	---



## WEAR METALS

Iron	ppm	█ 135	---	---	---
Copper	ppm	█ 11	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 1	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 4	---	---	---
Molybdenum	ppm	█ 8	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	1	---	---	---
Manganese	ppm	█ 12	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	█ 4038	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1664	---	---	---
Phosphorus	ppm	█ 1337	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 154	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0142  
**Unique No:** 11048073  
**Signed:** Wes Davis  
**Report Date:** 29 May 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

