



# CONSTRUCTION EQUIPMENT

SWA548445-20 VOLVO L60H 2528 - COOLANT



**Sample No:** VCP430346  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** SWA548445-20



## SAMPLE INFORMATION

Sample Number	VCP430346	---	---	---
Sample Date	17 May 2024	---	---	---
Machine Hours	2053	---	---	---
Sample Status	NORMAL	---	---	---

## ALTA EQUIPMENT

5985 COURT STREET ROAD  
 SYRACUSE, NY  
 US 13206  
 Contact: JIM STRIGLE  
 JIM.STRIGLE@ALTG.COM  
 T: (315)437-2611  
 F: (315)434-9471



## COOLANT CONDITION

pH	Scale 0-14	■ 7.31	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.3	---	---	---
Freezing Point	°C	■ -33	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO0142  
**Unique No:** 11048537  
**Signed:** Jonathan Hester  
**Report Date:** 30 May 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

