CONSTRUCTION EQUIPMENT HERC RENTALS VOLVO A30G 753512 - BOGIE/CENTER AXLE

Sample No:VCP449739Oil Type:{unknown}Job No:HERC RENTALS

VOLVO

SAMPLE INFORMATION

Sample Number		VCP449739	VCP436179		
Sample Date		22 May 2024	14 Oct 2023		
Machine Hours		1885	702		
Oil Hours		0	0		
Oil Changed		Not Changd	Changed		
Sample Status		NORMAL	NORMAL		
OIL CONDI	TION				
Visc @ 40°C	cSt	369	101		
CONTAMI					
				-	
Water	%	NEG	NEG		
Silicon	ppm	0	4		
Sodium	ppm	0	3		
Potassium	ppm	0	4		
VOLVO					
WEAR ME	TALS				
Iron	ppm	0	265		
Copper	ppm	0	12		
Lead	ppm	0	0		
Tin	ppm	0	0		
Aluminum	ppm	0	0		
Chromium	ppm	0	6		
Molybdenum	ppm	0	12		
Nickel	ppm	0	1		
Titanium	ppm	0	0		
Silver	ppm	0	0		
Manganese	ppm	0	15		
Vanadium	ppm	0	0		
VOLVO					

ADDITIVES Calcium 46 172 ppm Magnesium 0 0 ppm 75 Zinc ppm 1 Phosphorus 1090 137 ppm Barium ppm 0 3 233 303 Boron ppm



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0093

 Unique No:
 11056493

 Signed:
 Jonathan Hester

 Report Date:
 31 May 2024


 Contact/Location: KENNY HANEY - VOLVO0093

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06194370 (Generated: 05/31/2024 16:03:10) Rev: 1

Contact/Location: KENNY HANEY - VOLVO0093