CONSTRUCTION EQUIPMENT VOLVO A40G 352912 - TRANSMISSION (AUTO) 41850



Sample No: VCP453839

VOLVO

Job No:

41850

SAMPLE INFORMATION VCP453839 Sample Number VCP420561 Sample Date 22 May 2024 17 Jul 2023 Machine Hours 4094 2926 Oil Hours 0 0 Oil Changed Changed Not Changd NORMAL NORMAL Sample Status **OIL CONDITION** Visc @ 40°C 30.0 cSt 28.6 CONTAMINATION Water % NEG NEG 5 Silicon ppm 7 Sodium 6 🔲 3 ppm Potassium ppm 2 □ < 1 WEAR METALS 39 Iron ppm 17



215 - ASCENDUM MACHINERY INC - CAYCE

2303 AIRPORT BLVD CAYCE, SC US 29033 Contact: ROBBY HERLONG robby.herlong@ascendummachinery.com T: (803)394-6783 F: (803)791-9920

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Copper	ppm	18	10	
Lead	ppm	■ <1	0	
Tin	ppm	4	2	
Aluminum	ppm	22	12	
Chromium	ppm	□ <1	0	
Molybdenum	ppm	0	0	
Nickel	ppm	2	1	
Titanium	ppm	<1	0	
Silver	ppm	□ <1	0	
Manganese	ppm	1	<1	
Vanadium	ppm	<1	<1	
	5			
Calairea		- 254	- 71	

Calcium	ppm	251	71	
Magnesium	ppm	∎1	0	
Zinc	ppm	75	0	
Phosphorus	ppm	246	200	
Barium	ppm	0	0	
Boron	ppm	79	97	

Depot: VOLVO0013 Unique No: 11056607 Signed: Wes Davis Report Date: 30 May 2024 Contact/Location: ROBBY HERLONG - VOLVO0013

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

