



CONSTRUCTION EQUIPMENT

VOLVO A40G 752081 - TRANSMISSION (AUTO)



Sample No: VCP449929
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No:



SAMPLE INFORMATION

Sample Number	VCP449929	---	---	---
Sample Date	23 May 2024	---	---	---
Machine Hours	1342	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



OIL CONDITION

Visc @ 40°C	cSt	█ 27.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 7	---	---	---
Potassium	ppm	█ 3	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 30	---	---	---
Copper	ppm	█ 32	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 4	---	---	---
Aluminum	ppm	█ 18	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 70	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 4	---	---	---
Phosphorus	ppm	█ 183	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 75	---	---	---

Depot: VOLVO0090
Unique No: 11056611
Signed: Sean Felton
Report Date: 31 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS


Iron (ppm)



Lead (ppm)



Aluminum (ppm)




Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



Additives

