



CONSTRUCTION EQUIPMENT

VOLVO EC250EL 314172 - COOLANT



Sample No: VCP438770
Oil Type: VALVOLINE 50/50
Job No:



SAMPLE INFORMATION

Sample Number	VCP438770	---	---	---
Sample Date	14 May 2024	---	---	---
Machine Hours	3232	---	---	---
Sample Status	NORMAL	---	---	---

CITY CARTING
 221 OLD GATE LN
 MILFORD, CT
 US 06460
 Contact: TAVINS BANKS
 tavins@citycart.net
 T: (203)223-3885
 F:



COOLANT CONDITION

pH	Scale 0-14	■ 8.63	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.8	---	---	---
Freezing Point	°C	■ -35	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: CITMILCON
Unique No: 11056714
Signed: Jonathan Hester
Report Date: 03 Jun 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

