

CONSTRUCTION EQUIPMENT LKQ TAMPA VOLVO L110H 632741 - HYDRAULIC SYSTEM

Sample No: VCP444018

Oil Type: **VOLVO SUPER HYDRAULIC OIL 46**

Job No: **LKQ TAMPA**

SAMPLE II	NFORMATION					
Sample Number		VCP444018				
Sample Date		23 Apr 2024				
Machine Hours		1028				
Oil Hours		0				
Oil Changed		N/A				
Sample Status		NORMAL				
OIL CONDITION						
Visc @ 40°C	cSt	43.4				
Acid Number (AN)	mg KOH/g	■0.28				
CONTAMINATION						
Water	%	NEG				
Particles >4µm		6545				

water	70	IALO				
Particles >4µm		6545				
Particles >6µm		932				
Particles >14µm		■33				
ISO 4406:1999 (c)		20/17/12				
Silicon	ppm	6				
Sodium	ppm	■ <1				
Potassium	ppm					
WEAR METALS						
Iron	mag	10				

MENTAL METALS					
Iron	ppm	10			
Copper	ppm	2			
Lead	ppm	2			
Tin	ppm	-<1			
Aluminum	ppm	1			
Chromium	ppm	■ 3			
Molybdenum	ppm	-<1			
Nickel	ppm	■ <1			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	0			

ADDITI	VES			
Calcium	ppm	73	 	
Magnesium	ppm	10	 	
Zinc	ppm	441	 	
Phosphorus	ppm	■330	 	
Barium	ppm	■ 0	 	
Boron	ppm	■0	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot: VOLVO0093 **Unique No:** 11057472 Signed: Wes Davis Report Date: 31 May 2024



CONSTRUCTION EQUIPMENT





GRAPHS

