



CONSTRUCTION EQUIPMENT

562094 COVANTA VOLVO L220H 3339 - TRANSMISSION (AUTO)



Sample No: VCP450708
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 562094 COVANTA



SAMPLE INFORMATION

Sample Number	VCP450708	---	---	---
Sample Date	21 May 2024	---	---	---
Machine Hours	9447	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY

5210 REESE ROAD
 DAVIE, FL
 US 33314

Contact: N. FACEY
 nfacey@altaequipfl.com
 T: (954)581-4744
 F: (954)583-0318



OIL CONDITION

Visc @ 40°C	cSt	█ 27.9	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 54	---	---	---
Copper	ppm	█ 12	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 85	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 24	---	---	---
Phosphorus	ppm	█ 214	---	---	---
Barium	ppm	█ 3	---	---	---
Boron	ppm	█ 58	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0095
Unique No: 11057948
Signed: Wes Davis
Report Date: 31 May 2024



CONSTRUCTION EQUIPMENT



GRAPHS

