

CONSTRUCTION EQUIPMENT F03455 WIN-WASTE VOLVO L 150H 7370 - COOLANT



 Sample No:
 VCP116508

 Oil Type:
 {unknown}

 Job No:
 F03455 WIN-WASTE

SAMPLE IN	FORMATION				
Sample Number		VCP116508			
Sample Date		28 May 2024			
Machine Hours		10			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	8.47			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	NT NT			
Percentage Glycol	%	40.6			
Freezing Point	°C	-13			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Red			



CHADWICK-BAROSS INC

31 JAMES P. MURPHY INDUSTRIAL HWY WEST WARWICK, RI US 02893 Contact: SARAH YERGEAU sarah.yergeau@chadwick-baross.com T: F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:CHAWESRIUnique No:11058296Signed:Jonathan HesterReport Date:04 Jun 2024Contact/Location: SARAH YERGEAU - CHAWESRI

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

