

CONSTRUCTION EQUIPMENT 717229 VOLVO EC750 314108 - REAR RIGHT FINAL DRIVE



Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 717229

SAMPLE II	NFORMATION			
Sample Number	-	VCP454567	VCP431272	
Sample Date		24 May 2024	14 Nov 2023	
Machine Hours		3483	2548	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		ABNORMAL	ABNORMAL	
OIL CONDI	TION			
Visc @ 40°C	cSt	■284	277	
CONTAMIN	NATION			

CONTAN	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	189	△ 112	
Sodium	ppm	1	□ 0	
Potassium	ppm	2	3	
VOLVO				

WEAR I	METALS			
Iron	ppm	1163	<u> </u>	
Copper	ppm	■ 3	2	
Lead	ppm	0	0	
Tin	ppm	■0	0	
Aluminum	ppm	11	3	
Chromium	ppm	10	7	
Molybdenum	ppm	2	2	
Nickel	ppm	2	1	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	10	7	
Vanadium	ppm	0	0	

ADDITIVES					
Calcium	ppm	114	7 9		
Magnesium	ppm	17	1 6		
Zinc	ppm	43	40		
Phosphorus	ppm	■852	■829		
Barium	ppm	3	4		
Boron	ppm	122	117		



BLUE GOOSE GROWERS 16059 W ORANGE AVE FT PIERCE, FL

US 34945 Contact: SERVICE MANAGER

T: (772)461-3020

Diagnosis

We advise that you check all areas where dirt can enter the system. Resample at the next service interval to monitor. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.

Depot: **BLUFOR Unique No:** 11059201 Signed: Don Baldridge Report Date: 04 Jun 2024



CONSTRUCTION EQUIPMENT





