

## **CONSTRUCTION EQUIPMENT**

SPM716708 WASTE MGMT VOLVO L150H 633423 - HYDRAULIC SY

Sample No: VCP439875

Oil Type: AW HYDRAULIC OIL ISO 46

Job No: SPM716708 WASTE MGMT

WATION  VCP439875  21 May 2024 1956 0 Not Changd NORMAL  ### 42.7  KOH/g		
21 May 2024 1956 0 Not Changd NORMAL 42.7 KOH/g 0.31	   	
1956 0 Not Changd NORMAL  42.7  KOH/g		
0 Not Changd NORMAL  42.7  KOH/g		
Not Changd NORMAL    42.7   42.7   0.31     0.31     NEG   3692   764   57		 
NORMAL    42.7     KOH/g   0.31     N     NEG   3692     764     57		 
■ 42.7 KOH/g ■ 0.31 N NEG 3692 ■ 764 ■ 57		 
N NEG 3692 764 57		 
N NEG 3692 764 57		 
N NEG 3692 764 57		 
N NEG 3692 764 57		 
NEG 3692 764		 
3692 764 57		 
□ 764 □ 57		
57		
n <b>0</b>		 
_		 
n <b>0</b>		 
n <b>0</b>		 
n <b>0</b>		 
^		
n <b>0</b>		 
		1



### **ALTA EQUIPMENT CO - ORLAND PARK**

5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: MARK DEROSA mark.derosa@altg.com T: (248)356-5200

### Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO8885Unique No:11059692Signed:Wes DavisReport Date:04 Jun 2024

**65** 

**-**<1

**422** 

**332** 

**0** 

**0** 

**ADDITIVES** 

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

