



# CONSTRUCTION EQUIPMENT

SWA565009-10 VOLVO L150H 7023 - COOLANT



**Sample No:** VCP430317  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** SWA565009-10



## SAMPLE INFORMATION

Sample Number	<b>VCP430317</b>	VCP306392	---	---
Sample Date	<b>03 Jun 2024</b>	27 Dec 2021	---	---
Machine Hours	<b>3138</b>	351	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

### DENALI WE CARE

400 TORNE RD  
HILLBURN, NY  
US 10931  
Contact: Service Manager



## COOLANT CONDITION

pH	Scale 0-14	<b>7.39</b>	8.15	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	<b>NT</b>	0	---	---
Percentage Glycol	%	<b>46.4</b>	46	---	---
Freezing Point	°C	<b>-26</b>	-29	---	---

T:  
F:



## CONTAMINATION

Coolant Appearance	<b>normal</b>	normal	---	---
Coolant Color	<b>Yllow</b>	Yllow	---	---

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** DENHIL  
**Unique No:** 11072765  
**Signed:** Jonathan Hester  
**Report Date:** 13 Jun 2024




# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

