



CONSTRUCTION EQUIPMENT

SWA572466-10 VOLVO L120H 632789 - COOLANT



Sample No: VCP432316
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA572466-10



SAMPLE INFORMATION

Sample Number	VCP432316	VCP376118	VCP346892	VCP332264
Sample Date	30 May 2024	26 Oct 2022	04 May 2022	14 Jan 2022
Machine Hours	7044	4122	3072	2502
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

DUFFY LAYTON
 12 HUNNS LAKE RD
 STANFORDVILLE, NY
 US 12581
 Contact: Service Manager



COOLANT CONDITION

pH	Scale 0-14	7.16	7.24	7.36	7.30
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	0	NT
Percentage Glycol	%	54.1	57.7	57.1	58.0
Freezing Point	°C	-45	-52	-52	-54

T:
F:



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: DUFSTA
Unique No: 11072766
Signed: Jonathan Hester
Report Date: 13 Jun 2024




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

