

## **CONSTRUCTION EQUIPMENT** VOLVO A45G 752116 - DIESEL ENGINE



#### Sample No: VCP454779

**Oil Type:** VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

#### Job No:

VOLVO					
SAMPLE I	NFORMATION				
Sample Number		VCP454779		 	
Sample Date		04 Jun 2024		 	
Machine Hours		757		 	
Oil Hours		0		 	
Oil Changed		Changed		 	
Sample Status		ABNORMAL		 	
OIL CONDI	TION				
Visc @ 100°C	cSt	<b>10.7</b>		 	
Base Number (BN)		5.1		 	
Oxidation (PA)	%	61		 	
	70		-	 -	
VOLVO				 	
💛 Contamii	NATION				
Water	%	NEG		 	
Soot %	%	0.4		 	
Nitration (PA)	%	82		 	
Sulfation (PA)	%	61		 	
Glycol	%	NEG		 	
Fuel	%	<b>1.5</b>		 	
Silicon	ppm	30		 	
Sodium	ppm	2		 	
Potassium	ppm	3		 	
	le le				
VOLVO	TALC				
VEAR ME	IALS				
Iron	ppm	<b>31</b>		 	
Copper	ppm	<b>157</b>		 	
_ead	ppm	2		 	
Tin	ppm	7		 	
Aluminum	ppm	3		 	
Chromium	ppm	2		 	
Molybdenum	ppm	92		 	
Nickel	ppm	<u> </u>		 	
Titanium	ppm	<1		 	
Silver	ppm	0		 	
Manganese	ppm	2		 	
Vanadium	ppm	0		 	
	2			 	
Calcium	ppm	2199		 	
Magnesium	ppm	30		 	
Zinc	ppm	1142		 	
Phosphorus	ppm	940		 	
Barium		<b>940</b>		 	
	ppm	<b>1</b> 7			
Boron	ppm			 	



#### TA EQUIPMENT COMPANY

51 DR MARTIN LUTHER KING BLVD RT MYERS, FL 33905 ntact: TODD LARK k@altaequipfl.com 239)481-3302

### agnosis

and filter change at the time of mpling has been noted. No rrective action is recommended at is time. Resample at the next rvice interval to monitor.Valve wear indicated. All other metal levels are pical for a new component eaking in. Fuel content negligible. other contaminants were tected in the oil. The oil viscosity is wer than normal. The BN result dicates that there is suitable alinity remaining in the oil. onfirm oil type.

oot: VOLVO0090 Unique No: 11073570 Signed: Sean Felton Report Date: 17 Jun 2024

Contact/Location: TODD LARK - VOLVO0090

Report Id: VOLVO0090 [WUSCAR] 06206109 (Generated: 06/17/2024 13:44:51) Rev: 1


Page 1 of 2

# **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Contact/Location: TODD LARK - VOLVO0090