

# **CONSTRUCTION EQUIPMENT**

728681 RENTALS VOLVO A40G 752282 - HYDRAULIC SYSTEM



Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Oil Type: AW HYDRAULIC OIL ISO 46

**Job No:** 728681 RENTALS

CVMDILI	NFORMATION			
_	NI ORMATION	VCP454918	<u></u>	
Sample Number				 
Sample Date		05 Jun 2024		 
Machine Hours		1036		 
Oil Hours		0		 
Oil Changed		Not Changd		 
Sample Status		NORMAL		 
VOLVO				
OIL CONDI	TION			
Visc @ 40°C	cSt	<b>47.0</b>		 
Acid Number (AN)	mg KOH/g	■ 0.566		 
CONTAMIN	NATION			
Water	%	NEG		 
Particles >4µm		■3497		 
Particles >6µm		<b>1093</b>		 
Particles >14µm		<b>46</b>		 
ISO 4406:1999 (c)		19/17/13		 
Silicon	ppm	<b>■&lt;1</b>		 
Sodium	ppm	<b>■&lt;1</b>		 
Potassium	ppm	■0		 
WEAR ME	TALS			
Iron	ppm	<b>□</b> <1		 
Copper	ppm	<b>1</b>		 
Lead	ppm	<b>0</b>		 
Tin	ppm	<b>■</b> 0		 
Aluminum	ppm	<b>■</b> 0		 
Chromium	ppm	<b>■</b> 0		 
Molybdenum	ppm	<b>■</b> 0		 



### ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC

9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO096Unique No:11073893Signed:Don BaldridgeReport Date:13 Jun 2024

**Report Date:** 13 Jun 2024 Contact/Location: Robert LaPlante - VOLVO0096

**0** 

0

0

0

**48** 

**■**0

**305** 

**0** 

**0** 

**0** 

ppm

**ADDITIVES** 



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

