



# CONSTRUCTION EQUIPMENT

SWO-072572 APAC AL VOLVO L150G 23109 - COOLANT



**Sample No:** VCP442193  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** SWO-072572 APAC AL



## SAMPLE INFORMATION

Sample Number	<b>VCP442193</b>	VCP279708	---	---
Sample Date	<b>04 Jun 2024</b>	21 Oct 2020	---	---
Machine Hours	<b>4217</b>	1738	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

### COWIN EQUIPMENT COMPANY

2238 PINSON VALLEY PARKWAY  
BIRMINGHAM, AL  
US 35217

Contact: BRANTLY CLAY  
bclay@cowin.com

T:  
F: (205)856-2106



## COOLANT CONDITION

pH	Scale 0-14	<b>7.99</b>	8.07	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	<b>NT</b>	560	---	---
Percentage Glycol	%	<b>46.4</b>	44	---	---
Freezing Point	°C	<b>-26</b>	-25	---	---

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	<b>normal</b>	normal	---	---
Coolant Color	<b>Green</b>	Green	---	---

**Depot:** VOLVO8528  
**Unique No:** 11074491  
**Signed:** Jonathan Hester  
**Report Date:** 18 Jun 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

