

CONSTRUCTION EQUIPMENT VOLVO A25G 752602 - HYDRAULIC SYSTEM



Sample No: VCP0008747

Oil Type: AW HYDRAULIC OIL ISO 46

Job No:

VOLVO				
SAMPLE II	NFORMATION			
Sample Number		VCP0008747	 	
Sample Date		10 Jun 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
Visc @ 40°C	cSt	40.8	 	
Acid Number (AN)	mg KOH/g	■ 0.44	 	
VOLVO			 	
CONTAMIN	NATION			
Water	%	NEG	 	
Particles >4µm		862	 	
Particles >6µm		191	 	
Particles > 14µm		10	 	
ISO 4406:1999 (c)		17/15/10	 	
Silicon	ppm	4	 	
Sodium	ppm	■0	 	
Potassium	ppm	1	 	
WEAR ME	TALC			
_	IMC2			
Iron	ppm	7	 	
Copper	ppm	4	 	
Lead	ppm	3	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	2	 	
Chromium	ppm		 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIVE:				
Calcium	ppm	62	 	
Magnesium	ppm	■ <1	 	
Zinc	ppm	452	 	
Phosphorus	ppm	■322	 	
Barium	ppm	■0	 	
Boron	ppm	O	 	



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

F: (904)737-1260

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.

All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO0092Unique No:11075170Signed:Wes DavisReport Date:13 Jun 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





GRAPHS

