

CONSTRUCTION EQUIPMENT KOMATSU WA500-8 WP7225 - FRONT LEFT FINAL DRIVE



Sample No: VCP443404

Oil Type: KOMATSU 80W

Job No:

SAMPLE	E INFORMATIO	N		
Sample Number		VCP443404	 	
Sample Date		04 Jun 2024	 	
Machine Hours		9426	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CON	IDITION			
Visc @ 40°C	cSt	52.9	 	
Visc @ 40 C	CSt	32.9		
VOLVO			 	
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	10	 	
Sodium	ppm	■0	 	
Potassium	ppm	2	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	81	 	
Copper	ppm	4	 	
Lead	ppm	■<1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	-<1	 	
Molybdenum	ppm	1	 	
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	3300	 	
Magnesium	ppm	13	 	
Zinc	ppm	1393	 	
Phosphorus	ppm	1060	 	
Barium	ppm	0	 	
Boron	ppm	116	 	
DOION	ppiii	110		

LEGACY MATERIALS

5740 UTE CT VAN METER, IA US 50038 Contact: ALEX qc@legacymaterials.org T: (641)840-1326 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LEGVANUnique No:11075559Signed:Don BaldridgeReport Date:14 Jun 2024

Contact/Location: ALEX ? - LEGVAN



CONSTRUCTION EQUIPMENT





