



# CONSTRUCTION EQUIPMENT

## 729269 MACK CONCRETE VOLVO L110H 631841 - REAR AXLE



**Sample No:** VCP450710  
**Oil Type:** VOLVO WB 102  
**Job No:** 729269 MACK CONCRETE



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: KENNY HANEY  
 khaney@flaglerce.com  
 T: (813)630-0077  
 F: (813)630-2233



### SAMPLE INFORMATION

Sample Number	<b>VCP450710</b>	VCP405603	VCP363643	VCP278101
Sample Date	<b>11 Jun 2024</b>	28 Mar 2023	25 Aug 2022	18 Aug 2020
Machine Hours	<b>13345</b>	9800	7894	990
Oil Hours	<b>0</b>	0	0	0
Oil Changed	<b>Changed</b>	Not Changd	Not Changd	Changed
Sample Status	<b>NORMAL</b>	NORMAL	NORMAL	NORMAL



### OIL CONDITION

Visc @ 40°C	cSt	<b>43.1</b>	44.0	43.5	40.2
-------------	-----	-------------	------	------	------



### CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	<b>14</b>	19	16	22
Sodium	ppm	<b>6</b>	6	6	9
Potassium	ppm	<b>&lt;1</b>	2	2	1



### WEAR METALS

Iron	ppm	<b>99</b>	84	59	131
Copper	ppm	<b>0</b>	<1	<1	1
Lead	ppm	<b>0</b>	0	0	0
Tin	ppm	<b>&lt;1</b>	0	0	0
Aluminum	ppm	<b>2</b>	4	2	0
Chromium	ppm	<b>1</b>	1	1	4
Molybdenum	ppm	<b>1</b>	2	2	11
Nickel	ppm	<b>0</b>	<1	0	<1
Titanium	ppm	<b>0</b>	<1	<1	<1
Silver	ppm	<b>0</b>	0	0	<1
Manganese	ppm	<b>2</b>	2	1	7
Vanadium	ppm	<b>0</b>	0	0	0



### ADDITIVES

Calcium	ppm	<b>4006</b>	4071	3998	3719
Magnesium	ppm	<b>38</b>	31	31	10
Zinc	ppm	<b>1680</b>	1678	1662	1457
Phosphorus	ppm	<b>1318</b>	1369	1306	1215
Barium	ppm	<b>0</b>	0	<1	0
Boron	ppm	<b>152</b>	141	148	246

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0093  
**Unique No:** 11076506  
**Signed:** Wes Davis  
**Report Date:** 14 Jun 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

