



# CONSTRUCTION EQUIPMENT

975 INGERSOLL RAND XHP750 412633 - COOLANT



**Sample No:** VCP437465  
**Oil Type:** VOLVO COOLANT (GREEN)  
**Job No:** 975



## SAMPLE INFORMATION

Sample Number	VCP437465	---	---	---
Sample Date	01 May 2024	---	---	---
Machine Hours	1	---	---	---
Sample Status	NORMAL	---	---	---

**VCES- VOLVO CONSTRUCTION EQUIPMENT**  
 12345 MAPLEVIEW STREET  
 LAKESIDE, CA  
 US 92040  
 Contact: Mark Stewart  
 mark.stewart@vcesvolvo.com

T: X  
 F: X



## COOLANT CONDITION

pH	Scale 0-14	■ 9.14	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 1464	---	---	---
Percentage Glycol	%	■ 48.1	---	---	---
Freezing Point	°C	■ -31	---	---	---

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO4488  
**Unique No:** 11076590  
**Signed:** Jonathan Hester  
**Report Date:** 19 Jun 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

