



CONSTRUCTION EQUIPMENT

DOOSAN XHP750 412632 - COOLANT



Sample No: VCP437468
Oil Type: VOLVO COOLANT (GREEN)
Job No:



SAMPLE INFORMATION

Sample Number	VCP437468	---	---	---
Sample Date	01 May 2024	---	---	---
Machine Hours	2	---	---	---
Sample Status	NORMAL	---	---	---

VCES- VOLVO CONSTRUCTION EQUIPMENT
 12345 MAPLEVIEW STREET
 LAKESIDE, CA
 US 92040
 Contact: Mark Stewart
 mark.stewart@vcesvolvo.com
 T: X
 F: X



COOLANT CONDITION

pH	Scale 0-14	■ 9.21	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 1200	---	---	---
Percentage Glycol	%	■ 48.0	---	---	---
Freezing Point	°C	■ -31	---	---	---

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO4488
Unique No: 11076591
Signed: Jonathan Hester
Report Date: 19 Jun 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

