



CONSTRUCTION EQUIPMENT

578311 VOLVO L150H 7068 - COOLANT



Sample No: VCP430335
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 578311



SAMPLE INFORMATION

Sample Number	VCP430335	VCP367655	VCP365487	---
Sample Date	10 Jun 2024	31 Oct 2022	15 Aug 2022	---
Machine Hours	3722	1238	712	---
Sample Status	NORMAL	NORMAL	NORMAL	---

CALLANAN
 RT 32 677 FLATBUSH RD
 EAST KINGSTON, NY
 US 12401
 Contact:



COOLANT CONDITION

pH	Scale 0-14	7.31	7.73	8.33	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	0	---
Percentage Glycol	%	48.8	45.6	45.7	---
Freezing Point	°C	-31	-24	-24	---

T:
F:



CONTAMINATION

Coolant Appearance	normal	normal	normal	---
Coolant Color	Yllow	Yllow	Yllow	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: CALEAS
Unique No: 11076593
Signed: Jonathan Hester
Report Date: 19 Jun 2024




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

