CONSTRUCTION EQUIPMENT IAA VOLVO L90H 624521 - HYDRAULIC SYSTEM



**Sample No:** VCP437330

VOLV

Oil Type:	VOLVO SUPER HYDRAULIC OIL 46
Job No:	IAA

VOLVO					
SAMPLE I	NFORMATION				
Sample Number		VCP437330			
Sample Date		30 Apr 2024			
Machine Hours		8135			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		ATTENTION			
			-		
Visc @ 40°C	cSt	<b>43.5</b>			
Acid Number (AN)	mg KOH/g	0.35			
VOLVO					
CONTAMIN	VATION				

Water	%	NEG	 	
Particles >4µm		2589	 	
Particles >6µm		779	 	
Particles >14µm		🥚 106	 	
ISO 4406:1999 (c)	)	19/17/14	 	
Silicon	ppm	∎1	 	
Sodium	ppm	2	 	
Potassium	ppm	<b></b> <1	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

WE WE

VEAR M	ETALS			
Iron	ppm	2	 	
Copper	ppm	<b>  </b> <1	 	
Lead	ppm	□ <1	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	2	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	<1	 	

VOLVO

ADDITI	VES			
Calcium	ppm	57	 	
Magnesium	ppm	<b>4</b>	 	
Zinc	ppm	<b>491</b>	 	
Phosphorus	ppm	377	 	
Barium	ppm	0	 	
Boron	ppm	0	 	

 Depot:
 VOLVO0093

 Unique No:
 11082863

 Signed:
 Wes Davis


 Report Date:
 17 Jun 2024

## **CONSTRUCTION EQUIPMENT**



## GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06209999 (Generated: 06/17/2024 10:29:30) Rev: 1

Contact/Location: KENNY HANEY - VOLVO0093