



CONSTRUCTION EQUIPMENT

HERC RENTAL VOLVO A30G 752902 - BOGIE/CENTER AXLE



Sample No: VCP437334
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No: HERC RENTAL



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP437334	---	---	---
Sample Date	09 Apr 2024	---	---	---
Machine Hours	2093	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 221	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 105	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 5	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 398	---	---	---
Magnesium	ppm	█ 45	---	---	---
Zinc	ppm	█ 228	---	---	---
Phosphorus	ppm	█ 1097	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 161	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 11083366
Signed: Wes Davis
Report Date: 17 Jun 2024



CONSTRUCTION EQUIPMENT



GRAPHS

