VOLVO

CONSTRUCTION EQUIPMENT SWA543637 TADANO GR350XL 562450 - REAR AXLE



Sample No:	VCP453781
Oil Type:	GEAR OIL SAE 75W90
Job No:	SWA543637

SAMPLE INFORMATION

ORMATION				
v	CP453781	VCP440532		
3	1 May 2024	17 Nov 2023		
2	164	1147		
0		0		
С	hanged	Changed		
N	IORMAL	NORMAL		
Oll CONDITION OIL CONDITION @ 40°C cSt 111 187				
St	111	187		
TION				
%	NEG	NEG		
opm 🛛	6	14		
ppm	<1	2		
opm	_ <1	0		
	V 3 2 0 C N St TION	VCP453781 31 May 2024 2164 0 Changed NORMAL	VCP453781 VCP440532 31 May 2024 17 Nov 2023 2164 1147 0 0 Changed Changed NORMAL NORMAL N 111 St 111 6 NEG 0 144 10 144	VCP453781 VCP440532 31 May 2024 17 Nov 2023 2164 1147 0 0 Changed Changed NORMAL NORMAL NORMAL 187 St 111 187 6 NEG NEG opm 6 14

WFAR	METALS			
Iron		6	22	
	ppm	_		
Copper	ppm		1	
Lead	ppm	 <1	0	
Tin	ppm	0	0	
Aluminum	ppm	1	0	
Chromium	ppm		<1	
Molybdenum	ppm	 <1	<pre>1</pre>	
Nickel	ppm		0	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	□<1	5	
Vanadium	ppm	0	0	

ES				
ppm	0	8		
ppm		0		
ppm	3	8		
ppm	1383	1294		
ppm	0	2		
ppm	321	228		
	ppm ppm ppm ppm ppm	ppm 0 ppm <1	ppm 0 8 ppm <1	ppm 0 8 ppm <1



ALTA EQUIPMENT CO - ORLAND PARK

5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO8885

 Unique No:
 11083381

 Signed:
 Wes Davis

 Report Date:
 17 Jun 2024

 Contact/Location: DAVE ENG - VOLVO8885

CONSTRUCTION EQUIPMENT



VOLVO

