



CONSTRUCTION EQUIPMENT

VOLVO L60H 622532 - COOLANT



Sample No: VCP439882

Oil Type: {unknown}

Job No:



SAMPLE INFORMATION

Sample Number	VCP439882	---	---	---
Sample Date	10 Jun 2024	---	---	---
Machine Hours	11558	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.04	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 52.4	---	---	---
Freezing Point	°C	■ -40	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---



RECYCLE AMERICA

12100 YOUNG PINE RD

ORLANDO, FL

US 32829

Contact: SERVICE MANAGER

T:

F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: RECORL

Unique No: 11083523

Signed: Doug Bogart

Report Date: 18 Jun 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

