

CONSTRUCTION EQUIPMENT

SPM703638 ALPINE DEM VOLVO EC750E 314070 - DIESEL ENGINE

Sample No: VCP438292

Molybdenum

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ADDITIVES

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: SPM703638 ALPINE DEM

SAMPLE INFORMATION					
Sample Number	-	VCP438292	VCP415204		
Sample Date		30 Apr 2024	28 Sep 2023		
Machine Hours		2591	1522		
Oil Hours		0	0		
Oil Changed		Changed	Changed		
Sample Status		ATTENTION	NORMAL		
OIL CONDITION					
Visc @ 100°C	cSt	11.7	12.9		
Base Number (BN)	mg KOH/g	■7.8	■ 10.7		
Oxidation (PA)	%	59	78		
CONTAMINATION					
Water	%	NEG	NEG		
Soot %	%	■0.8	■1.2		
Nitration (PA)	%	56	65		
Sulfation (PA)	%	57	64		
Glycol	%	NEG	NEG		
Fuel	%	■ 0.4	<1.0		
Silicon	ppm	4	9		
Sodium	ppm	1	■3		
Potassium	ppm	■ <1	2		
WEAR ME	TALS				
Iron	ppm	■13	■28		
Copper	ppm	■ 2	1 1		
Lead	ppm	■ 0	< 1		
Tin	ppm	■ <1	1		
Aluminum	ppm	■ 3	2		
Chromium	ppm	■<1	- <1		

45

3

0

0

< 1</p>

0

1730

545

1153

944

0

47



ALTA EQUIPMENT CO - ORLAND PARK 5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VOLVO8885Unique No:11084084Signed:Sean FeltonReport Date:19 Jun 2024

Contact/Location: DAVE ENG - VOLVO8885

49

1

0

■0

0

970

817

1186

998

0

2



CONSTRUCTION EQUIPMENT





