CONSTRUCTION EQUIPMENT SW0-072798 APAC AL WEILER 2850A 1533 - REAR RIGHT FINAL D

Sample No:	VCP443984
Oil Type:	GEAR OIL SAE 90W140
Job No:	SWO-072798 APAC AL

VOLVO

VOLVO				
	E INFORMATION			- 680
Sample Number	-	VCP443984	 	
Sample Date		11 Jun 2024	 	 COWIN
Machine Hours		4072	 	 2238 PIN
Oil Hours		0	 	 BIRMING
Oil Changed		Changed	 	 US 352
Sample Status		NORMAL	 	 Contact:
				bclay@c
OIL CON	DITION			T: F: (205)8
Visc @ 40°C	cSt	308	 	
				р.
CONTAI	MINATION			Diagn Resamp
Water	%	NEG	 	 to mon
Silicon	ppm	8	 	 specifie
Sodium	ppm	1	 	 indicate
Potassium	ppm	1	 	 GEAR C
				confirm All com
WEAR I	METALS			There is
Iron	ppm	174	 	 contam
Copper	ppm	41	 	 condition the time
Lead	ppm	 <1	 	 the time
Tin	ppm	2	 	
Aluminum	ppm	2	 	
Chromium	ppm	1	 	
Molybdenum	ppm	 <1	 	
Nickel	ppm		 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITI	VES			
Calcium	ppm	40	 	

Calcium	ppm	40	 	
Magnesium	ppm	2	 	
Zinc	ppm	42	 	
Phosphorus	ppm	761	 	
Barium	ppm	 <1	 	
Boron	ppm	32	 	



EQUIPMENT COMPANY

NSON VALLEY PARKWAY GHAM, AL 17 **BRANTLY CLAY** owin.com 856-2106

osis

ble at the next service interval itor. The fluid was not d, however, a fluid match es that this fluid is (GENERIC) IL SAE 90W140. Please ponent wear rates are normal. no indication of any ination in the oil. The on of the oil is acceptable for e in service.


Depot: VOLVO8528 Unique No: 11085016 Signed: Wes Davis Report Date: 19 Jun 2024 Contact/Location: BRANTLY CLAY - VOLVO8528

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO8528 [WUSCAR] 06212152 (Generated: 06/22/2024 00:11:06) Rev: 1

Contact/Location: BRANTLY CLAY - VOLVO8528