

# CONSTRUCTION EQUIPMENT SW-35458-2 MAVERICK VOLVO L220H 3371 - REAR AXLE

Sample No: VCP454198 Oil Type: VOLVO WB 102

Job No: SW-35458-2 MAVERICK

VOLVO				
SAMPLE	INFORMATION			
Sample Number	-	VCP454198	 	
Sample Date		10 Jun 2024	 	
Machine Hours		3913	 	
Oil Hours		3913	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>50.2</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon		mEG	 	
Sodium	ppm	<b>1</b> 0	 	
Potassium	ppm	<b>■</b> 0	 	
Potassium	ppm	<u> </u>	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>■27</b>	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	<b>1</b>	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>□</b> <1	 	
Vanadium	ppm	0	 	
ADDITIV	IES			
Calcium	ppm	<b>2948</b>	 	
Magnesium	ppm	<b>1</b> 5	 	
Zinc	ppm	<b>1272</b>	 	
Phosphorus	ppm	<b>1245</b>	 	
Barium	ppm	■0	 	
Boron	ppm	20	 	



#### ARNOLD MACHINERY COMPANY

2975 WEST 2100 SOUTH SALT LAKE CITY, UT US 84119 Contact: TONY PAYAN tpayan@arnoldmachinery.com T: (801)972-4000 F: (801)975-9434

### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8770 **Unique No:** 11086716 Signed: Wes Davis Report Date: 20 Jun 2024



## **CONSTRUCTION EQUIPMENT**





