

CONSTRUCTION EQUIPMENT 717089 MOSAIC VOLVO EW 160E 3242

VOLVO EW 160E 324250 - DIESEL ENGINE

Sample No: VCP451463

Silicon

Sodium

Potassium

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

■8

1

-<1

ppm

ppm

ppm

Job No: 717089 MOSAIC

SAMPLE IN	NFORMATION				
Sample Number	-	VCP451463	VCP441973	VCP427328	
Sample Date		30 May 2024	31 Jan 2024	29 Sep 2023	
Machine Hours		1568	1027	584	
Oil Hours		500	500	500	
Oil Changed		Changed	Changed	Changed	
Sample Status		ATTENTION	ABNORMAL	ABNORMAL	
OIT CONDI.	TION				
Visc @ 100°C	cSt	12.2	11.9	0.6	
Base Number (BN)	mg KOH/g	■7.7	7.9	■ 5.1	
Oxidation (PA)	%	80	81	65	
CONTAMIN	ATION				
Water	%	NEG	NEG	NEG	
Soot %	%	■0.1	□0.1	□ 0.1	
Nitration (PA)	%	73	74	86	
Sulfation (PA)	%	59	62	58	
Glycol	%	NEG	NEG	NEG	
Fuel	%	<1.0	<1.0	■1.2	

WEAR	AETAL C				
WLAIL	IL I VL7				
Iron	ppm	4	■9	1 0	
Copper	ppm	11	<u>^</u> 71	1 90	
Lead	ppm	■ 0	1	2	
Tin	ppm	■0	_2	□ 3	
Aluminum	ppm	1	2	3	
Chromium	ppm	■0	 <1	- <1	
Molybdenum	ppm	■34	45	7 7	
Nickel	ppm	■0	_2	1	
Titanium	ppm	0	<1	0	
Silver	ppm	■0	0	□0	
Manganese	ppm	■ 0	2	■3	
Vanadium	ppm	0	<1	0	

15

_2

12

32

3

14

ADDITIVES						
Calcium	ppm	1657	1619	2186		
Magnesium	ppm	403	■351	43		
Zinc	ppm	970	■998	1234		
Phosphorus	ppm	■865	■839	■968		
Barium	ppm	0	1	□0		
Boron	ppm	15	1 9	1 7		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot: VOLVO0093 **Unique No:** 11087191 Signed: Don Baldridge Report Date: 21 Jun 2024



CONSTRUCTION EQUIPMENT





