

CONSTRUCTION EQUIPMENT SPM728584 FRITZ VOLVO 992G ADZOO488 - REAR AXLE



Sample No: VCP443760

Oil Type: **TDTO FLUID SAE 50** Job No: SPM728584 FRITZ

VOLVO SAMPLE	INFORMATIO	N		
Sample Number		VCP443760	 	
Sample Date		07 Jun 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	203	 	
	CSt	203	 	
VOLVO				
CONTAM	INATION			
Water	%	NEG	 	
Silicon	ppm	7	 	
Sodium	ppm	3	 	
Potassium	ppm	0	 	
	ррпп			
VOLVO				
WEAR M	1ETALS			
Iron	ppm	1 3	 	
Copper	ppm	■<1	 	
Lead	ppm	0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	 <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver		0	 	
Manganese	ppm	™ <1	 	
	ppm			
Vanadium	ppm	<1	 	
VOLVO				
ADDITIV	IES			
Calcium	ppm	■3271	 	
Magnesium	ppm	■13	 	
Zinc	ppm	■ 1262	 	
Phosphorus	ppm	1221	 	
Barium	ppm	0	 	
Boron		0	 	
DUIUII	ppm	U	 	

ALTA EQUIPMENT CO - ORLAND PARK

5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560

Diagnosis

F:

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8885 **Unique No:** 11087928 Signed: Sean Felton Report Date: 21 Jun 2024

Contact/Location: DAVE ENG - VOLVO8885



CONSTRUCTION EQUIPMENT





