

# CONSTRUCTION EQUIPMENT VOLVO A40G 752088 - FRONT AXLE



Sample No: VCP450813

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

CVMDIE	INFORMATIO	<b>V</b>		
	INFURMATIU			
Sample Number		VCP450813	 	
Sample Date		13 Jun 2024	 	
Machine Hours		1460	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>107</b>	 	
	CSL	107	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>3</b>	 	
Potassium	ppm	■3	 	
	ppiii			
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>265</b>	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>-&lt;1</b>	 	
Chromium	ppm	<b>4</b>	 	
Molybdenum	ppm	<b>1</b> 1	 	
Nickel	ppm	O	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b> 5	 	
Vanadium	ppm	<1	 	
	le le			
VOLVO	IFC		 	
ADDITIV	JEZ			
Calcium	ppm	<b>151</b>	 	
Magnesium	ppm	<b>2</b>	 	
Zinc	ppm	<b>67</b>	 	
Phosphorus	ppm	<b>1419</b>	 	
Barium	ppm	<b>1</b>	 	
Boron	ppm	■280	 	
	1			



### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK

tlark@altaequipfl.com T:

F: (239)481-3302

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot:VOLVO0090Unique No:11087948Signed:Sean FeltonReport Date:21 Jun 2024



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

