

# CONSTRUCTION EQUIPMENT VOLVO L70H 624045 - HYDRAULIC SYSTEM



Sample No: VCP0008461

Oil Type: AW HYDRAULIC OIL ISO 46

Job No:

CVMDIE	INFORMATION				
	INFUNMATION				
Sample Number		VCP0008461			
Sample Date		17 Jun 2024			
Machine Hours		0			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>42.8</b>			
Acid Number (AN	) ma KOH/a	■ 0.38			
	,				
CONTAMINATION					
LUNTAM	INATIUN				
Water	%	NEG			
Particles >4µm		8106			
Particles >6µm		<b>966</b>			
Particles >14µm		<b>6</b>			
ISO 4406:1999 (c)		20/17/10			
Silicon	ppm	<b>■</b> 3			
Sodium	ppm	■3			
Potassium	ppm	<b>■</b> 3			
WEAR M	ETALS				
Iron	ppm	<b>2</b>			
Copper	ppm	2			
Lead		<b>2</b>			
Tin	ppm	<b>0</b>			
Aluminum	ppm	<b>■</b> <1			
Chromium	ppm	<1			
	ppm	<b>0</b>			
Molybdenum Nickel	ppm	<b>■</b> <1			
Titanium	ppm				
Silver	ppm	0			
	ppm	0			
Manganese	ppm	<b>■&lt;1</b>			
Vanadium	ppm	0			
ADDITIV	ES				
Calcium	ppm	<b>65</b>			
Magnesium	ppm	<u> </u>			
Zinc	ppm	<b>455</b>			
Phosphorus	ppm	■351			
Barium	ppm	■0			
Boron	ppm	■0			
	le le				



### **ALTA EQUIPMENT COMPANY**

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

F: (904)737-1260

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.

All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0092

 Unique No:
 11088620

 Signed:
 Wes Davis

 Report Date:
 21 Jun 2024

Submitted By: TECHNICIAN ACCOUNT



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

