CONSTRUCTION EQUIPMENT A12634 VOLVO A35G 352266 - DROP BOX



Sample No:VCP454457Oil Type:MOBIL MOBILUBE HD 80W90

Job No: A12634

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

VOLVO

SAMPLE INFORMATION

3

0

0

10

0

61

12

337

2313

172

7



JAMES J ANDERSON

6958 TORRESDALE AVENUE PHILADELPHIA, PA US 19135 Contact: JOHN HERBUT herb@jjaconstruction.com T: (215)850-9051 F: (215)427-0208

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.The copper level has decreased, but is still abnormal. All other component wear rates are normal. The water content is negligible. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:JAAPHIUnique No:11088953Signed:Don BaldridgeReport Date:23 Jun 2024Contact/Location:JOHN HERBUT - JAAPHI

■ <1

0

0

<1

75

15

105

1328

4

21

8 🔲

ppm


ADDITIVES

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: JAAPHI [WUSCAR] 06216089 (Generated: 06/23/2024 13:05:49) Rev: 1

Contact/Location: JOHN HERBUT - JAAPHI