



CONSTRUCTION EQUIPMENT

A12804 VOLVO L90H 624901 - COOLANT



Sample No: VCP445292
Oil Type: EXTENDED LIFE COOLANT
Job No: A12804



SAMPLE INFORMATION

Sample Number	VCP445292	---	---	---
Sample Date	12 Jun 2024	---	---	---
Machine Hours	9790	---	---	---
Sample Status	NORMAL	---	---	---

WASTE MANAGEMENT - TELFORD
 400 PROGRESS DR
 TELFORD, PA
 US 18969-1191
 Contact: EDWARD ROGENER
 erogener@wm.com



COOLANT CONDITION

pH	Scale 0-14	■ 7.94	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 51.5	---	---	---
Freezing Point	°C	■ -38	---	---	---

T:
F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

Depot: WASTEL
Unique No: 11089126
Signed: Doug Bogart
Report Date: 24 Jun 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

