



CONSTRUCTION EQUIPMENT

SPM716537 MCIRON VOLVO A45GFS 353797 - TRANSMISSION (AUTO)



Sample No: VCP451383
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: SPM716537 MCIRON



SAMPLE INFORMATION

Sample Number	VCP451383	---	---	---
Sample Date	17 May 2024	---	---	---
Machine Hours	521	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT CO - ORLAND PARK
5000 INDUSTRIAL HWY
GARY, IN
US 46406
Contact: MARK DEROSA
mark.derosa@altg.com
T: (248)356-5200
F:



OIL CONDITION

Visc @ 40°C	cSt	█28.1	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█18	---	---	---
Sodium	ppm	█5	---	---	---
Potassium	ppm	█4	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█25	---	---	---
Copper	ppm	█19	---	---	---
Lead	ppm	█0	---	---	---
Tin	ppm	█3	---	---	---
Aluminum	ppm	█12	---	---	---
Chromium	ppm	█0	---	---	---
Molybdenum	ppm	█0	---	---	---
Nickel	ppm	█3	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█0	---	---	---
Manganese	ppm	█4	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█77	---	---	---
Magnesium	ppm	█2	---	---	---
Zinc	ppm	█7	---	---	---
Phosphorus	ppm	█215	---	---	---
Barium	ppm	█0	---	---	---
Boron	ppm	█80	---	---	---

Depot: VOLVO8885
Unique No: 11090095
Signed: Don Baldrige
Report Date: 24 Jun 2024



CONSTRUCTION EQUIPMENT



GRAPHS

