

CONSTRUCTION EQUIPMENT

589608 RENTALS VOLVO EC380EL 315360 - DIESEL ENGINE

Sample No: VCP454515

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: 589608 RENTALS

SAMPLE II	NFORMATION			
Sample Number		VCP454515	VCP432807	
Sample Date		18 Jun 2024	08 Nov 2023	
Machine Hours		2346	0	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ATTENTION	ABNORMAL	
VOLVO				
OIL CONDI	TION			
Visc @ 100°C	cSt	12.4	12.2	
Base Number (BN)	mg KOH/g	■7.0	9.4	
Oxidation (PA)	%	90	82	
VOLVO				
CONTAMIN	NATION			
Water	%	NEG	NEG	
Soot %	%	■0.1	0.1	
Nitration (PA)	%	83	63	
Sulfation (PA)	%	65	63	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	0.7	
Silicon	ppm	6	1 0	
Sodium	ppm	2	2	
Potassium	ppm	0	0	
WEAR ME	TALS			
Iron	ppm	7	■8	
Copper	ppm	15	△ 69	
Lead	ppm	■ <1	2	
Tin	ppm	■ 0	- <1	
Aluminum	ppm	1	1	
Chromium	ppm	■ 0	0	
Molybdenum	ppm	■ 51	4 5	
Nickel	ppm	■ 0	0	
Titanium	ppm	0	0	
Silver	ppm	■ 0	0	
Manganese	ppm	■ <1	- <1	
14 11		4	0	

0

1690

512

1197

975

0

38



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VOLVO0096Unique No:11090612Signed:Don BaldridgeReport Date:25 Jun 2024

Contact/Location: Robert LaPlante - VOLVO0096

1962

488

1274

1007

0

■8

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm ppm

ppm

ppm

ppm

ADDITIVES



CONSTRUCTION EQUIPMENT





