



CONSTRUCTION EQUIPMENT

RENTALS VOLVO A25G 740348 - TRANSMISSION (AUTO)



Sample No: VCP444691

Oil Type: DEXRON III

Job No: RENTALS



SAMPLE INFORMATION

Sample Number	VCP444691	VCP440044	VCP0007710	---
Sample Date	19 Jun 2024	18 Feb 2024	05 May 2023	---
Machine Hours	11853	11358	0	---
Oil Hours	0	0	0	---
Oil Changed	Not Chngd	N/A	N/A	---
Sample Status	NORMAL	ATTENTION	NORMAL	---



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	31.7	30.4	28.6	---
-------------	-----	-------------	------	------	-----



CONTAMINATION

Water	%	NEG	▲ 0.132	NEG	---
Silicon	ppm	6	4	4	---
Sodium	ppm	8	7	4	---
Potassium	ppm	4	3	2	---



WEAR METALS

Iron	ppm	37	35	33	---
Copper	ppm	11	9	8	---
Lead	ppm	0	1	0	---
Tin	ppm	3	2	3	---
Aluminum	ppm	16	16	15	---
Chromium	ppm	0	0	<1	---
Molybdenum	ppm	0	0	0	---
Nickel	ppm	2	<1	<1	---
Titanium	ppm	0	0	0	---
Silver	ppm	0	0	0	---
Manganese	ppm	2	<1	1	---
Vanadium	ppm	0	0	0	---



ADDITIVES

Calcium	ppm	83	76	80	---
Magnesium	ppm	2	0	0	---
Zinc	ppm	4	3	0	---
Phosphorus	ppm	216	188	204	---
Barium	ppm	0	<1	0	---
Boron	ppm	78	82	90	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 11096881
Signed: Wes Davis
Report Date: 25 Jun 2024



CONSTRUCTION EQUIPMENT



GRAPHS

