

# CONSTRUCTION EQUIPMENT SW0-072947 VOLVO EC480EL 315428 - COOLANT



Sample No: VCP443961

Oil Type: VOLVO COOLANT VCS (YELLOW)

**Job No:** SWO-072947

SAMPLE IN	FORMATION				
Sample Number	-	VCP443961	VCP447582		
Sample Date		21 Jun 2024	19 Dec 2023		
Machine Hours		1013	482		
Sample Status		NORMAL	NORMAL		
COOLANT	CONDITION				
рН	Scale 0-14	<b>7.93</b>	■8.11		
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■NT	■ NT		
Percentage Glycol	%	<b>■</b> 50.8	<b>51.3</b>		
Freezing Point	°C	<b>□</b> -35	<b>□</b> -38		
VOLVO					
CONTAMINATION					
Coolant Appearance		normal	normal		
Coolant Color		Yllow	Yllow		

### SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207

Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com T: (205)943-2268

F: (205)943-2269

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SAIBIRUnique No:11099981Signed:Jonathan HesterReport Date:28 Jun 2024



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

