CONSTRUCTION EQUIPMENT

Sample No:VCP454487Oil Type:EXTENDED LIFE COOLANTJob No:G08834 BCI-BLACKWOOD

VOLVO

SAMPLE INFORMATION					
Sample Number	-	VCP454487			
Sample Date		20 Jun 2024			
Machine Hours		15592			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	8.17			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	NT NT			
Percentage Glycol	%	50.9			
Freezing Point	°C	-35			
VOLVO					
Coolant Appearance		normal			
Coolant Color		Red			



HOFFMAN EQUIPMENT - DEPTFORD

1330 HURFFVILLE ROAD DEPTFORD, NJ US 08096 Contact: TAMMY SANDORA tammy.sandora@hoffmanequip.com T: (856)227-6400 F: (856)227-0046

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO8880

 Unique No:
 11100160

 Signed:
 Jonathan Hester

 Report Date:
 28 Jun 2024

 Contact/Location: TAMMY SANDORA - VOLVO8880

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

