

CONSTRUCTION EQUIPMENT X18706 VOLVO A40G 353135 - HYDRAULIC SYSTEM



Sample No: VCP433022

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No: X18706

VOLVO	NEODMATION			
SAMPLE I	NFORMATION			
Sample Number	-	VCP433022	 	
Sample Date		17 Jun 2024	 	
Machine Hours		4110	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL COND	ITION			
Visc @ 40°C	cSt	44.7	 	
Acid Number (AN)	mg KOH/g	■ 0.32	 	
VOLVO				
CONTAMI	NATION			
Water	%	NEG	 	
	70	671	 	
Particles >4µm			 	
Particles > 6µm		241	 	
Particles >14µm		27		
ISO 4406:1999 (c)		17/15/12	 	
Silicon	ppm	■7	 	
Sodium	ppm	2	 	
Potassium	ppm	0	 	
VOLVO				
WEAR ME	TALS			
Iron	ppm	7	 	
Copper	ppm	1	 	
Lead	ppm	■ <1	 	
Tin	ppm	0	 	
Aluminum	ppm	■ <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	3	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	■0	 	
Vanadium	ppm	0	 	
variaululii	ppiii	U		
VOLVO			 	
ADDITIVE	.2			
Calcium	ppm	57	 	
Magnesium	ppm	■0	 	



APAC BENTON
393 OREILLY RD
BENTON, MS
US 39039
Contact: WILL RATLIFF
will.ratliffjr@apac.com

T: (601)397-3696 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:APABENUnique No:11100476Signed:Wes DavisReport Date:28 Jun 2024

Contact/Location: WILL RATLIFF - APABEN

ppm

ppm

ppm

ppm

439

333

0

1

Zinc

Barium

Boron

Phosphorus



CONSTRUCTION EQUIPMENT





GRAPHS

