

CONSTRUCTION EQUIPMENT VOLVO A40G 352004 - COOLANT



Sample No: VCP0008447

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No:

Coolant Color

SAMPLE I	NFORMATION			
Sample Number	-	VCP0008447	VCP270416	
Sample Date		19 Jun 2024	27 Jan 2020	
Machine Hours		1032	1032	
Sample Status		NORMAL	NORMAL	
COOLANT	CONDITION			
рН	Scale 0-14	8.27	7.91	
Reserve Alkalinity	Scale 0-20			
Nitrites	ppm	NT NT	0	
Percentage Glycol	%	44.1	43	
Freezing Point	°C	-21	-22	
CONTAMI	NATION			
Coolant Appearance		normal	normal	

Yllow

Yllow



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256 Contact: SHAWN NORTHCRAFT shawn.northcraft@altg.com T: (904)737-6000 F: (904)737-1260

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO0092

 Unique No:
 11101013

 Signed:
 Jonathan Hester

 Report Date:
 01 Jul 2024

 Submitted By:
 EKNICIAN ACCOUNT

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

