

CONSTRUCTION EQUIPMENT G08925 RENTAL VOLVO L110H 631942 - COOLANT



 Sample No:
 VCP409988

 Oil Type:
 {unknown}

 Job No:
 G08925 RENTAL

SAMPLE IN	FORMATION			
Sample Number	-	VCP409988	 	
Sample Date		24 Jun 2024	 	
Machine Hours		3860	 	
Sample Status		NORMAL	 	
COOLANT	CONDITION			
рН	Scale 0-14	7.53	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	NT NT	 	
Percentage Glycol	%	50.1	 	
Freezing Point	°C	-35	 	
CONTAMIN	ATION			
Coolant Appearance		normal	 	
Coolant Color		Orange	 	



HOFFMAN EQUIPMENT - DEPTFORD

1330 HURFFVILLE ROAD DEPTFORD, NJ US 08096 Contact: TAMMY SANDORA tammy.sandora@hoffmanequip.com T: (856)227-6400 F: (856)227-0046

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO8880

 Unique No:
 11101273

 Signed:
 Jonathan Hester

 Report Date:
 01 Jul 2024

 Contact/Location: TAMMY SANDORA - VOLVO8880

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

