



# CONSTRUCTION EQUIPMENT

## VOLVO A40G 752090 - REAR AXLE



**Sample No:** VCP447790  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP447790	---	---	---
Sample Date	26 Jun 2024	---	---	---
Machine Hours	1363	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

**ALTA EQUIPMENT COMPANY**  
 5151 DR MARTIN LUTHER KING BLVD  
 FORT MYERS, FL  
 US 33905  
 Contact: TODD LARK  
 tlark@altaequipfl.com  
 T:  
 F: (239)481-3302



### OIL CONDITION

Visc @ 40°C	cSt	51.6	---	---	---
-------------	-----	------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	5	---	---	---
Sodium	ppm	3	---	---	---
Potassium	ppm	3	---	---	---



### WEAR METALS

Iron	ppm	241	---	---	---
Copper	ppm	2	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	3	---	---	---
Molybdenum	ppm	7	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	9	---	---	---
Vanadium	ppm	<1	---	---	---



### ADDITIVES

Calcium	ppm	109	---	---	---
Magnesium	ppm	1	---	---	---
Zinc	ppm	52	---	---	---
Phosphorus	ppm	2289	---	---	---
Barium	ppm	2	---	---	---
Boron	ppm	233	---	---	---

### Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

**Depot:** VOLVO0090  
**Unique No:** 11101988  
**Signed:** Don Baldrige  
**Report Date:** 01 Jul 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

