Sample No: VCP439817

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No: 730372 RENTALS

VOLVO	INCODMATION			
	INFORMATION	<u>.</u>		
Sample Number		VCP439817	 	
Sample Date		24 Jun 2024	 	
Machine Hours		1196	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	29.3	 	
VOLVO	WALE TION		 	
LONTAM	IINATION			
Water	%	NEG	 	
Silicon	ppm	16	 	
Sodium	ppm	6	 	
Potassium	ppm	2	 	
WEAR M	IETAI C			
_	IC I ML7			
Iron	ppm	■32	 	
Copper	ppm	■32	 	
Lead	ppm	■0	 	
Tin	ppm	4	 	
Aluminum	ppm	16	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	■0	 	
Nickel	ppm	■3	 	
Titanium	ppm	<1	 	
Silver	ppm	■0	 	
Manganese	ppm	■4	 	
Vanadium	ppm	<1	 	
VOLVO			 	
ADDITIV	ES			
Calcium	ppm	71	 	
Magnesium	ppm	- <1	 	
Zinc	ppm	6	 	
Phosphorus	ppm	■185	 	
Barium	ppm	■ <1	 	
Boron	ppm	69	 	
DOTOIT	ррпп	0 9		



ALTA EQUIPMENT COMPANY

5210 REESE ROAD DAVIE, FL US 33314 Contact: N. FACEY nfacey@altaequipfl.com T: (954)581-4744 F: (954)583-0318

Diagnosis

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of visible silt present in the sample. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0095Unique No:11102123Signed:Don BaldridgeReport Date:30 Jun 2024



CONSTRUCTION EQUIPMENT





GRAPHS

