

CONSTRUCTION EQUIPMENT SWA590217-20 VOLVO A30G 752316 - REAR AXLE



Sample No: VCP447051 **Oil Type:** {unknown}

Job No: SWA590217-20

SAMPLE	INFORMATION	N		
Sample Number		VCP447051	VCP379702	
Sample Date		20 Jun 2024	29 Nov 2022	
Machine Hours		3960	2557	
Oil Hours		0	0	
Oil Changed		N/A	Changed	
Sample Status		NORMAL	ABNORMAL	
		, , , , , , , , , , , , , , , , , , , ,		
VOLVO	DITION			
OIL CON	DITION			
Visc @ 40°C	cSt	■96.6	■99.8	
CUNTAN	MINATION			
_				<u>.</u>
Water	%	NEG	0.429	
Silicon	ppm	49	■33	
Sodium	ppm	4	0	
Potassium	ppm	■8	0	
VOLVO				
WEAR N	METALS			
Iron	ppm	756	□ 596	
Copper	ppm	75	4 4	
Lead	ppm	0	0	
Tin	ppm	4	- <1	
Aluminum	ppm	6	6	
Chromium	ppm	12	1 1	
Molybdenum	ppm	15	15	
Nickel	ppm	4	- <1	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	29	26	
Vanadium	ppm	0	0	
	•			
ADDITIV	/ES			
Calcium		715	712	
	ppm	10	10	
Magnesium Zinc	ppm		331	
	ppm	358		
Phosphorus	ppm	1480	1389	
Barium	ppm	4	8	
Boron	ppm	120	181	



ALTA EQUIPMENT COMPANY

5210 REESE ROAD
DAVIE, FL
US 33314
Contact: N. FACEY
nfacey@altaequipfl.com
T: (954)581-4744
F: (954)583-0318

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0095

 Unique No:
 11110077

 Signed:
 Wes Davis

 Report Date:
 03 Jul 2024

Contact/Location: N. FACEY - VOLVO0095



CONSTRUCTION EQUIPMENT





